

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5573	DATE	10 December 2024
MANUFACTURE	Hitachi Construction Machinery Co.,Ltd.		
DESCRIPTION OF DEFECT	In the turn signal lights of the shovel loader, due to inappropriate circuit protection control of the flasher relay, when the turn signal operating switch is rapidly switched from left to right or the emergency flasher switch is rapidly switched ON to OFF, the turn signal lights (front, side, rear, indicator lamp) may not light for a certain period of time (approximately 3 seconds).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
YDP-H88	「ZW100-6」	2024	1	
		TOTAL	1	