

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5574	DATE	10 December 2024
MANUFACTURE	Hitachi Construction Machinery Co.,Ltd.		
DESCRIPTION OF DEFECT	Some shovel loader axles have insufficient strength due to improper heat treatment of the axle shaft, which means that the heat treatment depth does not meet the standards. As a result, if continued use is continued, cracks may develop in the axle shaft, and in the worst case scenario, the axle shaft may break and cause the tire to fall off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
YDS-90C6	「ZW310-6」	2024	1	
		TOTAL	1	