

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 5 8 4	DATE	Dec. 12. 2024
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In the warning light lamps for emergency vehicle, rainwater or the like may penetrate into the electric wire due to the inappropriate waterproofing, and a short circuit on the board of the warning light lamps control unit for the side of the vehicle may occur. Therefore, the fuses for the side and rear warning light lamps are melt down, and there is no problem with the warning light lamps on the upper part of the front side of the vehicle, but there is a risk that other warning light lamps will not blink.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBF-CS8E26 3BF-CS8E26	PARAMEDIC	2018~2023	134
		TOTAL	134