

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5595	DATE	Dec. 12. 2024
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Some of the rear brake calipers may have insufficient tightening torque of the mount bolts, due to improper tightening process. Therefore, the bolts may get loosed and cause the abnormal noise when braking or driving over bumps, if the vehicle continues to be used in the above condition. In the worst case, the bolt may fall off and brake performance may be reduced.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
4AA-WDB3S	FRONX	2024	1,342	
4AA-WEB3S			569	
		TOTAL	1,911	