

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5597	DATE	December. 13. 2024
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for the side curtain airbag, when the swaging load of the clamp ring that secures the inflator and the airbag is inappropriately set, the clamp ring may be swaged by excessive load and lacks strength. For this reason, when the side curtain airbag deploys due to high temperatures inside the vehicle, the increased internal pressure of the inflator may break the clamp ring, preventing the airbag from deploying properly, which has the risk of not satisfying the passenger protection performance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAB- JJ3	「N-VAN」	2024	892
		TOTAL	892