

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5598	DATE	Dec. 16. 2024
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain brackets for fixing exhaust pipes of heavy-duty trucks, due to the inappropriate thickness of the paint film on the fastening part of the mounting bolts, the paint film may become thin by the heat from the engine, causing the bolts to become loose. Therefore, if it is used continuously, the bracket may fall off, causing a disruption to other traffic in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-FR1AHB	[HINO Profia]	2023～2024	805
2DG-FR1AHC			
2DG-FR1AHE			
2NG-FR1AHH			
2NG-FR1AHS			
2DG-FR1AJE		2023～2024	39
2DG-FS1AGE		2023～2024	539
2DG-FS1AHB		2023～2024	260
2DG-FS1AHC			
2DG-FS1AHE			
2DG-FS1AJE		2023～2024	206
2DG-FW1AHB		2023～2024	2, 307
2DG-FW1AHC			
2NG-FW1AHH			
2NG-FW1AHS			
		TOTAL	4, 156

Vehicles which had the affected parts installed after they rolled off the assembly line.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-FR1AHA	[HINO Profia]	2017～2021	292
2DG-FR1AHG			
2DG-FR1AHJ			
2NG-FR1AHH			
2DG-FR1AJA		2017～2018	4
2DG-FR1AJG			
2DG-FS1AGA		2017～2023	39
2DG-FS1AGE			
2DG-FS1AHA		2017～2020	32
2DG-FS1AHG			
2DG-FS1AHJ			
2DG-FS1AJA		2017～2020	20
2DG-FW1AHC			
2DG-FW1AHG		2017～2023	673
2DG-FW1AHJ			
2NG-FW1AHH			
2NG-FW1AHS			
2DG-FW1AJG		2017～2020	4
		TOTAL	1, 064

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS
Engine Assembly	11000E3110	2024	3
		TOTAL	3