

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5601	DATE	Jan.22.2025
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the fuel pump impeller, due to an improper injection molding process, the resin density of some impellers may be low and they deform by absorption of excessive fuel. If this were to occur, the impeller may interfere with the fuel pump body and fuel pump becomes inoperative, and in the worst case, resulting in engine stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-AGH30W	[ALPHARD]	2017-2018	44,514
DBA-AGH35W	[VELLFIRE]		5,002
DAA-AXVH70	[CAMRY]	2019	4,999
DBA-URZ100	[LC500]	2017-2019	36
DAA-GYL20W	[RX450h]	2019	4
DAA-GYL25W			2
DAA-GYL26W	[RX450hL]	2019	3
6AA-AXZH10	[ES300h]	2019	2
DAA-AXVH70N	[ALTIS]	2019	15
		TOTAL	54,577