

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5605	DATE	Feb. 6. 2025
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>The joint strength between the steering wheel and the steering column may be insufficient in some cases, due to the improper instruction in the drawing.</p> <p>Due to the above, the steering wheel mount nut may be loosened after receiving the rotation torque of the steering wheel operation, resulting in the excessive play in the joint portion or the abnormal noise. In the worst case, the steering wheel may be disconnected and the steering control may become impossible, if the vehicle was continuously used with the loosened steering nut.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
5AA-FF21S	IGNIS	2022~2023	719	Vehicles with leather steering wheel
5AA-MA37S	SOLIO	2022~2023	22,752	
5AA-MA47S			946	
4AA-MN71S	XBEE		6,948	
4BA-ZC33S	SWIFT		7,419	
5AA-ZC43S		2022	44	
5AA-ZC53S		2022~2023	1,242	
5AA-ZD53S		2022	385	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
4BA-ZC83S 5BA-ZC83S	SWIFT	2022~2023	811	Vehicles with leather steering wheel
5BA-ZD83S		2022	159	
5AA-MB37S	DELICA D:2	2022~2023	2,396	
		TOTAL	43,821	