VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5617	DATE	February 27, 2025	
MANUFACTURER	UD Trucks Corporation			
DESCRIPTION OF DEFECT	With regards to trucks/tractors with electronically controlled steering (UDAS), due to inappropriate inspection system setting and work instructions to tighten bolt which fixes steering column and column shaft, some bolts may not be tightened with designated torque value. Thus, the bolt may become loose and noise may occur whilst steering operation. If the vehicle continues operation under these conditions, the fitting parts of the column shaft may be worn out and it slides upon static steering operation, and might affect to steering operability.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-CG4FA	Quon	2023-2024	4	
2RG-CG5FA		2023-2024	4	
2RG-GK5DAB		2024	7	
2RG-GK5DAD		2024	2	
2DG-GW6ELH		2024	1	
2RG-EK5DAB	GIGA	2024	1	
2PG-EK6DAB		2024	1	
		TOTAL	20	