

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5611	DATE	March 4 ,2025
MANUFACTURER	AICHI Corporation		
DESCRIPTION OF DEFECT	<p>Some Shovel Loaders have insufficient tightening torque due to an inappropriate method of checking the tightening torque of bolts that fix the EGR.</p> <p>Therefore, in case of using the loader continuously as it is, the bolt may loosen and foreign object may be sucked in through the gap, damaging the prime mover and, in the worst case, the loader may be unable to run.</p> <p>To tighten the bolts fixing the EGR of all loaders with the specified torque.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-A5SDK7	TOYOTA JOBSUN	2024	3
YDN-A5SDK10	TOYOTA JOBSUN	2024	1
TOTAL			4