

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5626	DATE	Mar.6 2025
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	Due to improper manufacturing instructions, some left rear mounting brackets for the 6R30 engine have been installed with a wrong mounting bolt at the top. As a result, continued use of the vehicle may cause the relevant mounting bolt to loosen and fall off, affecting the safety of other traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-FS80VZ	「FUSO SUPER GREAT」	2024	1	
2PG-FS84VZ		2024～2024	119	
2PG-FS85VZ		2024	1	
2PG-FU80VY		2024	1	
2PG-FU84VZ		2024～2024	34	
2PG-FU85VZ		2024	1	
2PG-FV80VX		2024～2024	16	
2PG-FV80VY		2024	1	
2PG-FV80VZ		2024	1	
2PG-FV84VZ		2024	1	
2RG-FP84VDR		2024～2024	8	
2RG-FP84VER		2024～2024	9	
		TOTAL	193	