

# VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5619	DATE	March 10,2025
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	In the fuel pump of the shovel loader , due to insufficient design review of the threaded section for assembling the check valve, there are cases where the strength is insufficient. As a result, cracks have occurred in the threaded part when the check valve was assembled, and in the worst case, there is a potential risk of fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-WA129	「WA470-8」	2022-2024	10
YDS-WA142	「WA470-10」	2022-2024	31
TOTAL			41

Models of vehicles that may be used as service parts

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS-WA120	「WA470-7」	2013-2014	2
YDS-WA129	「WA470-8」	2017-2021	5
TOTAL			7

Pump ass'ys that were shipped as service parts and unknown to which units were used

PARTS NAME	PARTS NUMBER	SHIPPING YEAR	NUMBER OF PARTS
PUMP ASS'Y	600-815-9950	2023-2024	15
TOTAL			15