

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 6 2 7	DATE	Mar. 13. 2025
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In the connecting rod of the engine for power generation, there is a case that the screw thread of the fastening part is insufficient due to improper processing during manufacturing. Therefore, the connecting rod may be damaged due to insufficient fastening in the process of use, and then the power generation engine may be stopped. In the worst case, the vehicle may be unable to drive due to the insufficient electric power.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
6 AA-E 1 3 6 AA-SNE 1 3	NOTE	2 0 2 4	1 1
6 AA-FE 1 3 6 AA-FSNE 1 3	NOTE AURA		4
		TOTAL	1 5