VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5636	DATE	Mar.27 2025
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In some electric trucks, due to inappropriate software written in the steering wheel switches, the steering wheel switch on the trip meter control side may stop working, making it impossible to select the menu to be displayed in the meter cluster. As a result, the driver will not be able to easily check the mileage by operating the steering wheel switch, which may result in non-compliance with safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAB-FEAVK	「FUSO eCANTER」	2023~2024	1,190
ZAB-FEB8K		2023~2024	51
ZAB-FEBVK		2023~2024	3
ZAB-FEC9K		2023~2024	3
ZAB-FED9K		2023~2024	21
		TOTAL	1,268