

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	5 6 3 0	DATE	APRIL 4 , 2025
MANUFACTURER	NICHIGO CORPORATION		
DESCRIPTION OF DEFECT	<p>In the flexible exhaust pipe of a rotary snowplow vehicle, Due to insufficient design consideration, some of them are not strong enough.</p> <p>Therefore, if cracks occur due to vibrations caused by vehicle travel, and continued use causes the flexible pipe to break, resulting in exhaust gas leakage.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
R08D	HTR146	2013 R08D-0001	1
WDR-R08D	HTR146	2013~2019 R08D-0002~R08D-0098	96
R08E	HTR148	2016 [01] 111809	1
YDR-R08E	HTR148	2018~2024 R08E-0002~R08E-0095	89
R09D	KBR105	2013 [01] 062530	1
WDR-R09D	KBR105	2013~2018 R09D-0002~R09D-0068	63
R09E	KBR108	2016 [01] 111914	1
YDR-R09E	KBR108	2017~2024 R09E-0002~R09E-0100	77
R10D	HTR86	2015 R10D-0001	1
WDR-R10D	HTR86	2014~2018 R10D-0002~R10D-0143	133
R10E	HTR88	2016 [01] 111887	1
YDR-R10E	HTR88	2017~2024 R10E-0002~R10E-0190	160
TOTAL			624

【Notes】 The scope of the chassis number of the recalled vehicles, there is a case where the vehicle that do not qualify are also included.