

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5644	DATE	Apr. 16. 2025
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain electric wiring on left side of engines, due to insufficient design examination of the wiring, there are cases in which the wiring and peripheral parts such as the intercooler interfere with each other. Therefore, if it is used continuously, the insulation of the wiring may be damaged by engine vibration and so on, causing a fire due to a short circuit of the wiring in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-FC2ABA 2KG-FC2ABA 2KG-FC2ABG 2PG-FC2ABA 2PG-FC2ABG	[HINO Ranger]	2017~2022	30, 488
2DG-FD2ABA 2KG-FD2ABA 2KG-FD2ABG 2KG-FD2ABJ 2PG-FD2ABA 2PG-FD2ABG 2PG-FD2ABJ		2017~2022	26, 829
2DG-FE2ABA 2KG-FE2ABA 2KG-FE2ABG 2PG-FE2ABA 2PG-FE2ABG		2017~2021	7, 814
2DG-FE2ACA 2KG-FE2ACA 2KG-FE2ACG 2PG-FE2ACA 2PG-FE2ACG		2021~2022	482
2DG-FG2ABA 2KG-FG2ABA 2PG-FG2ABA		2017~2022	237

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-FJ2ABA 2KG-FJ2ABA 2KG-FJ2ABG 2PG-FJ2ABA 2PG-FJ2ABG	[HINO Ranger]	2017～2021	2, 406
2DG-FJ2ACA 2KG-FJ2ACA 2KG-FJ2ACG 2PG-FJ2ACA 2PG-FJ2ACG		2021	148
2KG-FX2ABA		2017～2022	402
2DG-GC2ABA 2DG-GC2ABG 2KG-GC2ABA 2KG-GC2ABG 2PG-GC2ABA 2PG-GC2ABG		2017～2022	2, 757
2DG-GD2ABA 2KG-GD2ABA 2KG-GD2ABG 2PG-GD2ABA 2PG-GD2ABG		2017～2022	2, 909
2DG-GK2ABA 2KG-GK2ABA		2017～2022	1, 512
2KG-GX2ABA 2PG-GX2ABA		2017～2022	1, 501
		TOTAL	77, 485