VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5645	DATE	April. 17. 2025		
MANUFACTURER	HONDA MOTOR CO., LTD.				
DESCRIPTION OF DEFECT	Some front suspension systems may have a problem of low fastening power due to insufficient management of tightening a nut fixing a damper mount to the damper unit, which resulted in uneven manufacture quality. This may rattle and loosen the damper unit at the part where the unit is fastened with a rod when steering, applying too much stress to the area near the fastening part. If the vehicle continues to be used without fixing it, the rod may be broken, spoiling driving stability in the worst-case scenario.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
DBA-JW5	「S660」	2015~2018		24,147
		2018~2019		3,599
3BA-JW5		2019~2022		5,950
			TOTAL	33,696