

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5651	DATE	May 22,2025
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	The console cover of the shovel loader (canopy model) has insufficient waterproofing design, which may allow rainwater or car wash water to seep into the console. Continued use of the vehicle in this condition could result in water seeping into the junction connector in the console, causing an internal short circuit or corrosion of the terminals, and in the worst case scenario, making the vehicle unable to be driven.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-WA139	WA80-8	2019-2025	54
TOTAL			54