

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5659	DATE	May. 22. 2025
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	The Automatic Collision Notification system does not automatically reconnect after the connection is interrupted due to being out of the service area during the call connection because the control program of the telematics control unit is inappropriate. Therefore, it does not comply with safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6AA-FL4	「CIVIC」	2025	1
			TOTAL
			1