

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5653	DATE	May. 29. 2025
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>The clearance between the pump case and the feeding impeller in the low pressure fuel pump was insufficient, due to the improper verification of the swelling value of the resin made impeller, and the impeller may interfere with the pump case as it is swollen with the fuel composition. The above may result in the fuel pump malfunction. In the worst case, it could cause the engine stalling while driving.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
CBA-ZC33S	SWIFT	2017～2022	32,798	
4BA-ZC33S			23,948	
		TOTAL	56,746	