

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5655	DATE	May. 29. 2025
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Some sealing bolts that fasten a lower case to the motor have low sealing performance when they are fastened due to inappropriate inspection jig management and molding method, which resulted in the molding defects in their thread parts. For this reason, if the vehicle continues to be used without any repairs, the engine oil may leak and adhere to the exhaust pipe(s), emitting smoke, and in the worst-case scenario, the oil may adhere to the rear tire, overturning the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	MEMO
8BL-RH17	「CB650R」 「CBR650R」	2024～2025	876	
8BL-SC86	「CB1000 HORNET」 「CB1000 HORNET SP」		503	
8BL-RH24	「CB750 HORNET」		451	
8BL-SC91	「NT1100P」		196	Emergency Vehicle
8BL-SC87	「Rebel 1100」 「Rebel 1100 T」	2025	10	
8BL-SC83		2024	2	
8BL-RD16	「XL750 TRANSALP」	2025	3	
		TOTAL	2,041	