

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5660	DATE	Jun.5 2025
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In some lateral rod & stabilizer brackets, the inner plate is only temporarily welded due to improper welding instructions. If the vehicle continues to be used in this condition, the bracket may crack.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2TG-MS06GP	「FUSO AERO ACE」	2023 ~ 2024	198
	「FUSO AERO QUEEN」	2023 ~ 2024	48
		TOTAL	246