

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5664	DATE	June 12, 2025
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	<p>In brake light switches on the shovel loader and motor grader, the position adjustment of the piston and microswitch relative to the thickness of the diaphragm, an internal component, is inappropriate, which can cause the microswitch to lose conductivity in low-temperature environments.</p> <p>As a result, there is a possibility that the brake light does not turn on even when the brake pedal is pressed.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDP-WA138	WA100-8	2023-2024	689
YDP-WA138	WA150-8	2023-2024	160
YDR-WA137	WA200-8	2023-2024	261
YDR-WA136	WA270-8	2023-2024	102
YDR-WA135	WA320-8	2023-2024	99
YDS-WA130	WA380-8	2023-2024	66
YDS-WA129	WA470-8	2023-2024	1
YDS-WA142	WA470-10	2023-2024	13
YDR-GD035	GD405-7	2023-2024	63
YDS-GD032	GD675-6	2023-2024	46
TOTAL			1500