

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5667	DATE	June. 19. 2025
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In a low-pressure fuel pump improvement measure, some packages containing incorrect gaskets were shipped out due to inappropriate packaging work of the parts for the improvement measure. If the incorrect gasket is assembled for the improvement measure, it will cause insufficient sealing between the fuel pump and the fuel tank, creating a risk of fuel leakage when the tank is filled up.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6AA-RC4	「ODYSSEY」	2017～2019	7,469
DAA-RC4		2017	761
DBA-RC1		2017～2019	63
DBA-JF4	「N-BOX」 「N-BOX Custom」	2017～2019	2,233
6BA-JF4		2019～2020	183
DAA-FR4	「JADE」	2017～2019	1,421
HBD-JJ2	「N-VAN」	2018～2020	430
6BA-JH4	「N-WGN」 「N-WGN Custom」	2019～2020	93
		TOTAL	12,653