

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5671	DATE	June. 19. 2025
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for the fuel pump, an incorrect fuel pump has been assembled due to inappropriate repair parts management at the factory. This makes the fuel gaging equipment caught on a component inside the fuel tank so that the fuel level warning light does not indicate correctly. If the vehicle keeps running without eliminating the causes of defects, it will run out of fuel, and the engine will stop while the vehicle is running, unable to restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-NC65	「CBR400R」	2024	2
		TOTAL	2