

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5669	DATE	Jun. 26 2025
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In some vehicles, the inner parts of the electric parking brake (EPB) are defectively manufactured. When the brakes are operated or released, the brake system may stop by detecting an overcurrent. If this happens, the braking force may be insufficient or the brakes may drag. In addition, the EPB warning light (amber) in the meter cluster comes on, but if continued to drive without noticing brake drag, the brakes may become hot. In the worst case, the surrounding parts may cause a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAB-FEAVK	「FUSO eCANTER」	2023～2025	1,760
ZAB-FEB8K		2023～2025	88
ZAB-FEBVK		2023～2024	7
ZAB-FEC9K		2023～2025	3
ZAB-FED9K		2023～2024	27
		TOTAL	1,885