

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5675	DATE	Jun.26.2025
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In an electric air compressor that supplies air to the brake air tank, due to insufficient consideration of heat resistance of the internal bearings, there is a possibility that the bearings may burn out, causing the compressor's rotation speed to decrease and the air pressure to drop. As a result, a warning light may come on and a warning sound may sound, and if the vehicle is continuously operated under this condition, the parking brake may not be able to be released, and the vehicle may become unable to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
ZBC-MUM1NAE	[SORA]	2018-2023	161	
		TOTAL	161	