

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ☒ Import Vehicles

CAMPAIGN No.	5687	DATE	8. July. 2025
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Due to insufficient consideration about the method for securing the camshaft of the engine, there are cases where the axial force of the tightened bolt for the plate that secures the camshaft is not enough. Therefore, if the vehicle continues to be used under the condition, the bolt may become loose and cannot secure the camshaft, and in the worst case, the engine stall and become unable to restart.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-SG42J	XMAX250	2017～2021	7,356
8BK-SG70J	XMAX250	2021～2023	1,587
2BL-SH15J	TRICITY 300	2020～2021	1,382
8BL-SH21J	TRICITY300	2023	93
		TOTAL	10,418