

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ Import Vehicles

CAMPAIGN NO.	5685	DATE	July 10 ,2025
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		Some flywheel housings of the Isuzu-manufactured-medium-duty trucks are not tightened with the specified torque because the instructions for tightening the plate cover mounting bolts in the manufacturing process are inappropriate. Therefore, if the vehicle continues to be used as it is, the bolts become loose, and in the worst case, the bolts and the plate cover fall off during running, which may obstruct traffic on the road.	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FVR26U4□ 2PG-FVR26U4	[FORWARD]	2024-2025	21
2DG-FVZ26U4		2024-2025	116
2KG-BVR26U4□ 2PG-BVR26U4	[CONDOR]	2024	4
2DG-BVZ26U4		2024-2025	22
		TOTAL	163