

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	5686	DATE	July 10 ,2025
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	In the braking device of some Isuzu-manufactured-medium-duty trucks, the nylon tube may come off from the connector due to the swing of the cab because the mounting position of the brake valve and the connector is offset to the right and left, and the shape of air piping (nylon tube) for the rear wheel brake is improper. Therefore, the supply of air to the rear wheel brake may be cut off, resulting in a possible functional failure of the rear wheel brake.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FRR90S4□ 2PG-FRR90T4□ 2RG-FRR90S4□ 2RG-FRR90T4	[FORWARD]	2023-2025	539
2PG-FSR90T4□ 2RG-FSR90S4□ 2RG-FSR90T4		2023-2025	114
2PG-BRR90T4□ 2RG-BRR90S4□ 2RG-BRR90T4	[CONDOR]	2024-2025	71
2RG-BSR90T4		2024	2
		TOTAL	726