

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	5690	DATE	July 15, 2025
MANUFACTURE	TOYOTA INDUSTRIES CORPORATION		
DESCRIPTION OF DEFECT	Bush press-inserted in engine fan used for cooling radiator of engine-powered forklifts may be insufficiently clinched, due to improper equipment condition settings at each production lot, resulting in abnormal noise. If this condition persists, the bush may break causing the fan to detach and potentially leading to engine overheating. In the worst-case, overheating might result in engine damage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
408FDL18	TOYOTA GENE0	2025	28
		TOTAL	28