

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicles

CAMPAIGN No.	5695	DATE	Jul.16.2025
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In seat covers, the processing method for the covering material was not sufficiently considered, which resulted in some of them spreading fire faster than the standards for combustion tests, and they did not comply with safety standards.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
5BA-NRE161	[COROLLA Axio]	2024-2025	1,178	
3BA-NZE161			1,219	
3BA-NZE164			604	
6AA-NKE165			2,293	
5BA-NRE161G	[COROLLA FIELDER]		1,208	
3BA-NZE161G			145	
3BA-NZE164G			1,768	
6AA-NKE165G			4,138	
		TOTAL	12,553	

The affected parts shipped as repair parts, and could possibility the vehicles equipped with them.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
5BA-NRE161	[COROLLA Axio]	2023	1	
		TOTAL	1	

The affected parts shipped as repair parts, and could possibility the vehicles equipped with them.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS	NOTE
Driver's seat cushion cover	71071-1AS40	2024-2025	5	
Passenger's seat cushion cover	71072-1AR30		1	
Driver's seat back cover	71073-13D30		2	
Passenger's seat back cover	71074-13F00		4	
Rear seat cushion cover	71075-13D70		1	[For COROLLA FIELDER HEV]
	71075-1AJ50		5	[For COROLLA Axio HEV]
	71075-1AJ60		1	[For FF]
Rear seat back cover	71077-1AF40		1	
		TOTAL	20	