

# VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5688	DATE	July 17, 2025
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	There are fuel tanks in which the seal surfaces of the fuel fillers were partially dented due to improper manufacturing control. Therefore, the rubber packing attached to the fuel tank cap cannot follow the concavity of the seal surface of the fuel filler, the airtightness is lowered, and there is a possibility that the amount of fuel evaporated gas emission does not satisfy the regulation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BK-DS12E	V-STROM	2024	313
8BK-DN12B	GSX250R	2024	107
		TOTAL	420