VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5698	DATE	Jul.24 2025		
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation				
DESCRIPTION OF DEFECT	Due to insufficient software considerations in the SSAM (Single Signal Detection and Actuation Module), the microcomputer in the SSAM may deem it to be faulty when the SSAM is booted or during booting, causing the microcomputer to repeat the reset. This may result in the engine not starting, not restarting, not switching off the engine or in the electrical devices not being activated or being forced to activate. (SSAM: body controller unit with integrated consumer control and power distribution for cab and body)				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-BE740E	「FUSO ROSA」	2024~2024	66
2RG-BE740G		2024~2024	461
2RG-BE740J		2024~2025	118
2RG-BG740G		2024~2024	123
		TOTAL	768

The affected parts shipped as repair parts, but the vehicle with them installed, cannot be identified.

PARTS NAME	PARTS NO.	SHI	PMENT YEAR	NUMBER OF PARTS
CONTROL UNIT, SAM, CABIN	MX996102	2024~2025		574
			TOTAL	574