

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5696	DATE	July 25, 2025
MANUFACTURER	KUBOTA Corporation		
DESCRIPTION OF DEFECT	About the power transmission of combine harvester, due to an improper design, the welds on the tension arm fulcrum shaft were partially insufficient to penetrate. As a result, the vibrations and shocks caused by the operation of the machine cause stress to concentrate on the areas where the welds have partially insufficient penetration, and in the worst case, the tension arm fulcrum shaft may break and the vehicle become unable to move.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-C438	DR472	11/7/2023~4/3/2024	618
		TOTAL	618