VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5699	DATE	Jul.25,2025			
MANUFACTURER	TADANO LTD.					
DESCRIPTION OF DEFECT	On some cranes, tightening torque for torque rod and lateral rod mounting bolts may be insufficient. Therefore, if the crane is continued to be used as it is, the mounting bolts may be damaged and torque rod remove from axle, and axle rattling (abnormal noise) occurs during driving.					

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLES
TADANO	「GR-250N-5」		2021 - 2025	892
TADANO	「GR-250N-4」	2021 - 2025		95
TADANO	「eGR-250N-1」		2024 - 2025	2
KOBELCO	「RK250-10」	2024 - 2025		5
KOBELCO	「RK250-9」	2022		2
			TOTAL	996