## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Import Vehicles

CAMPAIGN NO.	5700	DATE	July 30 ,2025
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		On certain supply pumps used for replacement and repair, due to an inappropriate surface treatment process, the strength may be insufficient. Therefore, cracks may develop when repeatedly operated under high load, causing fuel to leak.	

Vehicles Which Had The Affected Parts Installed After They Rolled Off The Assembly Line

+ through which flow the fill through the manufacture flow of the fill the fill through the fill the fill through the fill the fill through th				
ТҮРЕ	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE	
PKG-RU1ESAJ	[ISUZU GALA]	2007-2008	2	
		TOTAL	2	

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF□ VEHICLE
Supply Pump	5-86548817-0	2025	1
		TOTAL	1