

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5701	DATE	Jul. 30. 2025
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain supply pumps used for replacement and repair, due to an inappropriate surface treatment process, the strength may be insufficient. Therefore, cracks may develop when repeatedly operated under high load, causing fuel to leak.		

Vehicles which had the affected parts installed after they rolled off the assembly line.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KS-FN1EWJA	[HINO Profia]	2004	1
BDG-FQ1EWYG		2008	3
BDG-FR1EPYA		2008	1
KS-FR1EXWG		2003	1
ADG-FR1EXYA		2006~2010	8
ADG-FR1EXYG			
BDG-FR1EXYG			
BKG-FR1EXYG			
BKG-FR1EXYJ			
KS-FR1EZWG		2004	1
KS-FS1EKJA		2005	1
ADG-FS1EKXA		2006~2008	5
BDG-FS1EKXA			
ADG-FS1EPYA		2006~2006	2
KS-FS1ETWA		2004	1
KS-FS1EZWA		2004	1
ADG-FS1EZYA		2006~2007	3
BDG-FS1EZYA			
BDG-FS1EZYG			
KS-FW1EXWG		2004~2005	3
PK-FW1EXWG			
ADG-FW1EXYG		2006~2010	6
BDG-FW1EXYG			
BDG-FW1EXYJ			
BKG-FW1EXYJ			
BDG-FW1EZYJ			
PK-SH1EDJG		2007	1
		2004	2

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-SH1EDXG	[HINO Profia]	2006～2007	5
BDG-SH1EDXG			
BKG-SH1EDXG			
BKG-SH1EGXG		2006	1
ADG-RU1ESAA	[HINO Selega]	2006～2008	3
PKG-RU1ESAA			
		TOTAL	49

The affected parts shipped as repair parts, but the vehicles with them installed, cannot be identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS
Supply pump	22100E0303	2024～2025	11
		TOTAL	11