

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5697	DATE	July 31, 2025
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	Due to improper parts management during manufacturing, brake caliper assemblies from different model were installed in some cases. As a result, the brake pads cannot press the brake disc at the correct position during braking, the braking force is lowered, and in the worst case, the rear brake may not work.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BK-ED22Y	GIXXER	2023-2024	6
		TOTAL	6