

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5704	DATE	August 8, 2025
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	In the transmission system of a shovel loader, the sensor that measures the rotational speed of the output shaft may detect an abnormality due to slight gear vibrations occurring during forward/reverse switching while the vehicle is stationary. This can trigger a fault code, causing the transmission to shift to neutral and potentially preventing the vehicle from moving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDS-WA142	「WA470-10」	2019-2025	72
TOTAL			72