

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5708	DATE	August. 28. 2025
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for some speedometers, due to inappropriate management of the jigs that paint the front brake panel on which the speedometer cable is assembled, the paint adheres to a hole for insertion of the said cable, making the diameter of the hole smaller. Because of this, pushing the cable hard into the hole at the time of assembly may bend the tip of the cable so that the tire rotation will not be transmitted, thereby inhibiting the speedometer from working in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BH-AA09	「SuperCub50」	2024～2025	2
		TOTAL	2