

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5707	DATE	29 August 2025
MANUFACTURE	Hitachi Construction Machinery Co.,Ltd.		
DESCRIPTION OF DEFECT	<p>Due to insufficient design considerations regarding the mounting bolts for the front underguard of shovel loaders, the bolts may become loose due to twisting caused by external forces during operation. Therefore, if the shovel loaders continues to be used in this condition, the bolts may break, and in the worst case scenario, the front underguard may fall off.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
UDS-H73	「ZW310-5B」	2015	4	
YDS-90C6	「ZW310-6」	2017	17	
		TOTAL	21	