## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5713	DATE	Sep.2 2025
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	In some high-pressure fuel pipes between the engine's common rail and the injectors, the tightening torque of the injector-side mounting nuts may be insufficient due to an improper tightening method. Therefore, engine vibrations can cause the nuts to loosen, leading to fuel leaks.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FEBS0	「FUSO CANTER」	2025	1
2RG-FBA20		2025	1
2RG-FBA30		2025	1
2RG-FBA60		2025	1
2RG-FEAV0		2025	1
2RG-FEB50		2025~2025	4
		TOTAL	9