

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5712	DATE	September.4.2025
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In electric heaters, the durability of the heating element is insufficient due to insufficient design consideration. Therefore, if you continue to use it as it is, the inside of the element may be damaged, and in the worst case, the heater will stop working and the defrosting performance reduces and may not remove frost and/or fog from the windshield glass.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
2KG-XZB70 ”kai”(modified)	[TOYOTA COASTER]	2021	4	modified car
2KG-GDB70 ”kai”(modified)		2023	1	
ZAA-KMA10	[UX300e]	2021-2023	640	
		TOTAL	645	

The affected parts shipped as repair parts, and could possibility the vehicles equipped with them.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
ZAA-KMA10	[UX300e]	2021	2	
		TOTAL	2	