

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5715	DATE	September. 4. 2025
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for some continuously variable transmissions, due to inappropriate instructions for input shaft assembly, an O-ring is not assembled on the said shaft. For this reason, the hydraulic pressure of the forward clutch drops during high load driving and, in the worst case, the clutch slips, flashing the warning light and activating failsafe, which may result in poor acceleration.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6BA-JH3	「N-WGN」	2025	1
		TOTAL	1