

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5716	DATE	September. 4. 2025
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	As for electric wiring, due to inappropriate swaging of the connector for the left steering switch harness wires, when the harness repeatedly slides by the steering operation, the swaged part of the connector may become worn away. For this reason, if nothing is done about it and the vehicle continues to be used, the swaged part may get oxidized, increasing the resistance value, so that the alarming horn could not beep and/or the headlamp could not turn on the driving beam.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-SD10	「CRF1100L Africa Twin」	2019～2021	1,604
8BL-SD10		2021～2023	755
8BL-SD15		2023～2025	601
		TOTAL	2,960