

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 7 1 4	DATE	Sep. 11. 2025
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In electric power generation motors of e-POWER vehicles, the amount of insulation material (varnish) applied to the stator may be small due to improper control of the amount of varnish applied to the stator. Therefore, the insulation resistance decreases will be occurred due to the insulation failure, and if the vehicle is continued to be used, the e-POWER system warning light is turned on and a warning message is displayed. And the power generation motor will stop generating electricity, and the EV battery may not be able to be supplied with power and may not be able to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
6 AA-T 3 3 6 AA-SNT 3 3	X-TRAIL	2 0 2 2 ~ 2 0 2 3	9, 1 9 7
TOTAL			9, 1 9 7