

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5720	DATE	September 25, 2025.
MANUFACTURER	Mazda Motor Corporation		
	On the fuel pipe, due to improper criteria values for the retaining force applied by the bracket, the retaining force of some parts are low. If the vehicle is driven for extended periods at high engine speeds, such as during track driving, vibrations could cause the fuel pipe to enter a resonant state and develop cracks. Continued use in this condition may lead to a fuel leak, resulting in engine stalling and prevent vehicle from restarting. Additionally, a fuel leak can increase the risk of a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ND5RC	「ROADSTER」	2015-2018	18,491
		Total	18,491