

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5722	DATE	Sep. 30. 2025
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On some fuel system injectors, parts may not be strong enough due to an improper molding process of the injector body. Therefore, repeated high-load operation can cause cracks in the injector, leading to fuel leakage into the engine, causing engine damage and, in the worst case, a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-FR1AHA	[HINO Profia]	2019	215
2DG-FR1AHG			
2DG-FR1AHJ			
2NG-FR1AHS			
2DG-FR1AJA		2019	21
2DG-FS1AGA		2019	102
2DG-FS1AHA		2019	50
2DG-FS1AHG			
2DG-FS1AHJ			
2DG-FS1AJA		2019	46
2DG-FW1AHG		2019	682
2DG-FW1AHJ			
2NG-FW1AHH			
2NG-FW1AHS			
2DG-FW1AJG		2019	16
2DG-FW1AJJ			
		TOTAL	1, 132

Vehicles which had the affected parts installed after they rolled off the assembly line.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-FR1AHA	[HINO Profia]	2018	2
2DG-FR1AHG			
2DG-FS1AGA		2017～2018	8
2DG-FW1AHG		2018	4
		TOTAL	14