

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5721	DATE	Oct. 1, 2025
MANUFACTURER	SHO—SHIN Co, Ltd.		
DESCRIPTION OF DEFECT	Due to improper electrical circuit design considerations in the starter switch of agricultural chemical spraying vehicles, an overcurrent may flow through the starter switch depending on the operating conditions of the electrical equipment. This may cause the resin inside the starter switch to melt, resulting in poor contact of the contacts and, in the worst case scenario, causing the engine to stall and become unable to be restarted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBT—J7	3S—FSC600TLG	2016—2021	106
	3S—FSC601TLG	2022—2025	42
	3S—FSC1000TLG	2016—2021	123
	3S—FSC1001TLG	2022—2025	60
		TOTAL	331